

=====

K E N W O O D

>>> A M A T E U R R A D I O S E R V I C E B U L L E T I N <<<

=====

Kenwood Service Centers

Kenwood Service Corporation
2201 East Dominguez Street
Long Beach, California 90801
Telephone 1-310-639-5300

Kenwood Service Center, East
829 Lynnhaven Parkway, Suite 130
Virginia Beach, Virginia 23452
Telephone 1-804-340-1702

=====

AMATEUR RADIO SERVICE BULLETINS BY NUMBER
UPDATED January 3, 1995

ASB-0001	DELETED	DELETED
ASB-0002	TS-520	NOVICE OPERATION - 75 WATTS
ASB-0003	QR-666	VFO STABILITY IN SWL RECEIVER
ASB-0004	TS-520	AM BROADCAST INTERFERENCE
ASB-0005	TS-700A	REPEATER OPERATION MODIFICATION (EUROPE)
ASB-0006	T-599D	CHAIN DRIVE MODIFICATION
ASB-0007	T-599A/D	SERVICE NOTES
ASB-0008	R-599A/D	SERVICE NOTES
ASB-0009	TS-820S	SPEECH PROCESSOR ALIGNMENT
ASB-0010	TR-7400A	FINAL UNIT ARCING
ASB-0011	TR-2200A	ANTENNA ADAPTER
ASB-0012	TS-820	AUX BAND INSTALLATION (RX ONLY)
ASB-0013	TS-820	RIT MODIFICATION
ASB-0014	TS-820	MICROPHONE INPUT ATTENUATOR
ASB-0015	VOX-3	SENSITIVITY AND DELAY
ASB-0016	TR-8300	RECIEVER/TRANSMITTER ALIGNMENT
ASB-0017	T-599D	REDUCING 120HZ HUM
ASB-0018	TR-7400A	VARIOUS SERVICE NOTES
ASB-0019	DG-1	NEW DISPLAY TUBE
ASB-0020	TS-700A	SERVICE NOTES
ASB-0021	TS-520	SERVICE NOTES
ASB-0022	TR-2200A	SERVICE NOTES
ASB-0023	TR-7200A	SERVICE NOTES
ASB-0024	TS-820S	SERVICE NOTES
ASB-0025	DG-5	REPAIR OF RCA PLUGS/JACKS
ASB-0026	DG-1	SERVICE NOTE / BAD SOLDER JOINTS
ASB-0027	TS-700A	9 VOLT REGULATOR REPLACEMENT
ASB-0028	DG-5	REPAIR NOTES
ASB-0029	TS-5	THEORY OF OPERATION
ASB-0030	TS-820S	GENERAL ALIGNMENT PROCEDURE
ASB-0031	R-599A/D	REMOVING CB BAND
ASB-0032	TR-7400A	CHANGES IN PD UNIT OF IC'S
ASB-0033	RM-76	FREQUENCY ERROR WITH TR-7600/7625
ASB-0034	TR-7400A	METER LAMP LONGER LIFE
ASB-0035	MC-45/TR-7400A	MODIFICATION FOR USE WITH TR-7400A
ASB-0036	TS-180S	HUM WITH PS-30/ERRATIC DFC
ASB-0037	TS-120S	VOX OPERATION PICK-UP TIME
ASB-0038	TS-120S	FINAL TRANSISTOR REPLACEMENT
ASB-0039	TR-7600/7625	ALTERNATOR WHINE
ASB-0040	TS-120S	ANTENNA INPUT TRANSFORMER REPLACEMENT

ASB-0041	BS-8/SM220/TS-180	ALIGNMENT WITH TS-180S/SM220
ASB-0042	TS-180S	IF #2 OUTPUT LEVEL FOR SM220 OPERATION
ASB-0043	TS-520S	-6VDC SUPPLY FAILURE
ASB-0044	TS-120S/180S	PHONE PATCH TERMINAL ADDITION
ASB-0045	TR-7600/7625	AUDIO TONE ON TX
ASB-0046	TS-520S	CW FREQUENCY SHIFT
ASB-0047	TS-180S	INCREASE OF RX AUDIO OUTPUT
ASB-0048	TS-120S	HUM IN SSB TX
ASB-0049	MANY	OPTIONAL FILTER LIST
ASB-0050	TR-7600/7625	OPTIONAL CERAMIC FILTER
ASB-0051	TS-120S	FINAL PROTECTION
ASB-0052	TS-520/SM220/BS5	SM-220/BS-5 SWEEP INTERFERENCE
ASB-0053	DG-1	SERVICE NOTES (PC BOARD SOLDER)
ASB-0054	DG-5	SERVICE NOTES (PC BOARD SOLDER)
ASB-0055	TS-180S	ALC LOSS OR REDUCTION ON 40 METERS
ASB-0056	TS-180S	DFC/HUM/INTERMITTANT FREQ STABILITY
ASB-0057	SM-220	SHIELD INSTALLATION/SWEEP INTERFERENCE
ASB-0058	TR-2400	TONE ENCODER RFI/MOTORBOATING
ASB-0059	RM-76	BATTERY BACK-UP POWER
ASB-0060	TS-120S	REPAIR NOTES
ASB-0061	TS-180S	TROUBLE SHEET/REPAIR NOTES
ASB-0062	DK-520/DG-5	USE WITH TS-511/TS-900/T/R-599
ASB-0063	TS-520	IF OUT FOR SM-220
ASB-0064	TS-120S	FULL CW OUTPUT IN SSB MODE (USE SB-944)
ASB-0065	TR-7600/7625	RF POWER MODULE RETURNS (OBSOLETE)
ASB-0066	SM-220	FEEDBACK FROM BS-8
ASB-0067	TS-180S	DFC INSTABILITY
ASB-0800	DELETED	DELETED
ASB-0801	TS-120S	TX OSCILLATION (USE SB-844)
ASB-0802	RM-76	MICROPROCESSOR FAILURE
ASB-0803	TS-180S	CW DELAED KEYING DURING CW VOX OPERATION
ASB-0804	TR-7625	INTERMITTENT TX
ASB-0805	R-1000	MUTING OPERATION - OPS MANUAL UPDATE
ASB-0806	TR-7600/7625	MEMORY BATTERY BACK-UP
ASB-0807	TR-2400	OPTIONAL CHARGE INPUT PROTECTION
ASB-0808	TR-2400	OFFSET FAILURE
ASB-0809	TR-2400	UNWANTED NOISE: TONE OR BURST AT TX
ASB-0810	TR-2400	DISPLAY OR KEYBOARD TROUBLE
ASB-0811	TR-2400	RX LOW, INTERMITTENT, OR DISTORTED
ASB-0812	TS-520S/820S	CW FILTER SELECT CONTROL
ASB-0813	R-1000	AGC, AM BANDWIDTH CHANGES
ASB-0814	TR-2400	PLL UNLOCK / LOW CRYSTAL ACTIVITY
ASB-0815	TR-2400	PULSE NOISE IN RECEIVE OR TRANSMIT
ASB-0816	TS-120S	BAND PASS FILTER CHANGE - IMPROVE SELECTIVITY
ASB-0817	TS-180S	LINEAR AMPLIFIER OPERATION / SWITCHING TIMES
ASB-0818	TR-2400	SCRATCHY TX AUDIO
ASB-0819	TR-2400	VOLUME CONTROL REPLACEMENT - PRECAUTIONS
ASB-0820	TR-7625	FINAL MODULE REPLACEMENT (USE SB-826)
ASB-0821	TS-120S	TX OSCILLATION (SEE ASB-844)
ASB-0822	TR-2400	BATTERY CHARGER FAILURE / REPAIR
ASB-0823	R-1000	RF ATTENUATOR 10 DB STEP OPTION
ASB-0824	TR-9000	CW/SSB TX INSTABILITY / FM'ING / CHIRP ON CW
ASB-0825	TR-9000	TX PULSE NOISE IN SSB TRANSMISSION
ASB-0826	TR-7625	HYBRID AMPLIFIER MODULE SUBSTITUTION
ASB-0827	TS-120S	VFO INSTABILITY AND DRIFT
ASB-0828	TR-7800	TONE PAD CONVERSION FOR 4TH COLUMN (ABCD)
ASB-0829	TR-7800	INTERMITTANT LOSS OF MEMORY

ASB-0830	TR-2400	EXCESSIVE BACKGROUND NOISE ON XMIT
ASB-0831	TS-120S	ANT INPUT TRANSFORMER REPLACEMENT (NEW PART)
ASB-0832	TS-120S	FULL CW OUTPUT IN SSB MODE (SEE ALSO ASB-844)
ASB-0833	TR-7800/9000	OPTIONAL FILTERS TO IMPROVE SELECTIVITY
ASB-0834	TR-7800	PULSE NOISE AND SPKR BUZZ DURING XMIT
ASB-0835	DELETED	DELETED
ASB-0836	TR-7800	CONTINUOUS CHARGE FOR INTERNAL BATTERIES
ASB-0837	TS-830S	OPERATION ON 240V AC
ASB-0838	VFO-230	OPERATION ON 240V AC
ASB-0839	TS-180S	VFO INSTABILITY / DRIFT IMPROVEMENT
ASB-0840	TS-830S	INTERMITTANT FREQUENCY SHIFT
ASB-0841	TR-7800	DISPLAY FAILURE CAUSED BY FAILURE OF CLOCK
ASB-0842	DS-2/TS-520/820	REPLACEMENT FOR DS-1A IN TS820/TS520
ASB-0843	TR-8400	SUB-AUDIBLE ENCODER INSTALLATION
ASB-0844	TS-120S	TX OSCILLATION ESPECIALLY ON 10-15-20 METERS
ASB-0845	TR-8400	RX INTERNAL SPURIOUS SIGNALS
ASB-0846	TR-7850	RF LED METER DISPLAYS LOW READING
ASB-0847	TS-830S	LOW VOLTAGE SUPPLY DRIFT/IMPROVEMENTS
ASB-0848	TS-530S	LOW VOLTAGE SUPPLY / OPTIONAL IMPROVEMENTS
ASB-0849	TR-9000	XMIT SIDEBAND DISTORTION / CARRIER BALANCE
ASB-0850	TS-180S	ALC LEVEL IMPROVEMENT / LPF CHANGES
ASB-0851	TS-830S	NOISE BLANKER IMPROVEMENTS / CROSS MODULATION
ASB-0852	MC-46	DTMF OPERATION WITH OLDER EQUIPMENT
ASB-0853	TR-8400	TRANSMITTER FREQUENCY RESPONSE VOICE AND DTMF
ASB-0854	TR-7730	TRANSMITTER FREQUENCY RESPONSE VOICE AND DTMF
ASB-0855	TR-8400	TRANSMIT/RECEIVE SWITCH TIME / PLL LOCKUP
ASB-0856	TS-660	MICROPROCESSOR LATCH-UP
ASB-0857	TS-830S	TRANSMITTER "TALKBACK" FROM RF INTRUSION
ASB-0858	TR-2500	RX IMD IMPROVEMENT
ASB-0859	TR-9000	STABILITY IMPROVEMENT / PLL UNLOCK
ASB-0860	TR-7800/7850	MEMORY CH. 7 INDICATOR ERRATIC
ASB-0861	TR-7800/7850	MEMORY RETENTION IMPROVEMENTS
ASB-0862	VFO-120	DIAL LAMP SWITCHING CIRCUIT
ASB-0863	TS-930S	INCORRECT LINE VOLTAGE SETTING
ASB-0864	SMC-25	MODIFICATION FOR USE WITH THE TR-2400
ASB-0865	TS-430S	500 KHZ HETERODYNE
ASB-0866	TS-930S	CW HETERODYNE TONE WITH VBT CONTROL
ASB-0867	TS-930S	SSB TX AUDIO TONE QUALITY SN < 3080001
ASB-0868	TS-930S	LOSS OF RX SENSITIVITY
ASB-0869	TS-930S	PLL UNLOCK / BLANK DISPLAY
ASB-0870	TR-7930/7950	RX INTERFERENCE FROM FM/TV BROADCAST
ASB-0871	TR-9130	LOW DRIVE LEVEL / LOW OUTPUT POWER
ASB-0872	TS-930S	CW PITCH TONE SHIFT WHEN MONI SWITCH IS ON
ASB-0873	TS-930S	CW VBT - SIMPLIFIED ALIGNMENT
ASB-0874	TS-930S	RF FEEDBACK WHEN USING EXTERNAL SPEAKER
ASB-0875	TS-930S	RX AUDIO OSCILLATION
ASB-0876	TS-930S	RF FEEDBACK INTO MIC CIRCUIT
ASB-0877	AT-930	SERVICE NOTES
ASB-0878	TS-530S	IF UNIT Q2, Q7 PROTECTION
ASB-0879	TS-930S	ALC LEVEL DRIFT AT 28 MHZ
ASB-0880	TM-201/401	INCREASED TX AUDIO / MIC GAIN
ASB-0881	TS-930S	POWER SUPPLY SURGE PROTECTION
ASB-0882	TS-430S	NOTCH CONTROL/BETTER ADJUSTMENT
ASB-0883	TS-430S	AM WIDE/NARROW FILTER SELECTION
ASB-0884	TS-930S	15 MTR INTERNAL BEAT NOTE
ASB-0885	TS-430S	INTERNAL BEAT AT 28.415 & 21.526
ASB-0886	TS-930S	INTERMITTENT TX POWER OUTPUT

ASB-0887	TS-430S	NOISE BLANKER IMPROVEMENTS
ASB-0888	TS-430S	INTERMITTENT PLL UNLOCK IN FM/AM
ASB-0889	INTERNAL	DELETED
ASB-0890	INTERNAL	DELETED
ASB-0891	TS-430S	DELETED, SUPERCEDED BY #0895
ASB-0892	TM-411	LOW/NO RECEIVER SENSITIVITY
ASB-0893	TS-930S	NOISY POWER SUPPLY FAN
ASB-0894	INTERNAL	DELETED
ASB-0895	TS-430S	PLL UNLOCK AT HIGH TEMPERATURE
ASB-0896	TS-940S	LCD CLOCK DISPLAY ERRATIC OPERATION
ASB-0897	TM-211/411	AF GAIN CONTROL PART CHANGE
ASB-0898	INTERNAL	DELETED
ASB-0899	INTERNAL	DELETED
ASB-0900	TS-940S	PLL UNLOCK
ASB-0901	TR-2600A	PLL UNLOCK (TROUBLESHOOTING)
ASB-0902	TS-430S	LOW/INTERMITTENT RX / LPF RELAYS
ASB-0903	TR-2600A	PLL UNLOCK CAUSED BY OSC FAILURE
ASB-0904	TM-2550	DCL CALL SIGN DATA LOSS
ASB-0905	MANY	COAX CABLE WITH PLUG LIST
ASB-0906	TM-2570	LOW TX POWER OUTPUT WITH GOOD VSWR
ASB-0907	TS-940S	ANTENNA TUNER RELAY DAMAGE / MODIFICATION
ASB-0908	TS-940S	PLL UNLOCK DUE TO LOW LEVELS
ASB-0909	TS-940S	AVR UNIT CAPACITOR CHANGE / FAILURE
ASB-0910	TS-940S	AGC CIRCUIT IMPROVEMENTS
ASB-0911	TS-940S	DELETED, SUPERCEDED BY #0917
ASB-0912	TS-940S	TRANSMITTER HUM IN SSB
ASB-0913	TS-940S	SIGNAL TO NOISE RATIO IMPROVEMENT WITH NB
ASB-0914	HMC-1	NOT TO BE USED WITH TH-205AT/TH-215A
ASB-0915	INTERNAL	DELETED
ASB-0916	PS-50	AVR FAILURE /IMPROVED SURGE PROTECTION
ASB-0917	TS-940S	VCO/CARRIER TO NOISE RATIO IMPROVEMENTS
ASB-0918	TS-940S	SQUELCH SWITCHING NOISE SN < 711XXXX
ASB-0919	R-5000	NO FREQUENCY CHANGE THROUGH COMPUTER
ASB-0920	TH-205/215	PROTECTION FUSE REPLACEMENT WITH DIODE
ASB-0921	TS-940S	SSB TALK POWER IMPROVEMENT S/N 601XXX-708XXX
ASB-0922	RC-10	HANG UP TIME/TIMEOUT TIMER SETTINGS/XBAND RPT
ASB-0923	INTERNAL	DELETED
ASB-0924	INTERNAL	DELETED
ASB-0925	TM-3530A	NOISY TRANSMIT AFTER WARMUP
ASB-0926	TW-4100A	REPEATER STOP SCAN ON THE UHF BAND
ASB-0927	RC-10	ALTERNATOR NOISE IN MIC CIRCUIT
ASB-0928	TS-140S	INTERMITTENT LOSS OF TRANSMIT POWER
ASB-0929	TS-140S	MOMENTARY TRANSMISSION WHEN VOX IS TURNED ON
ASB-0930	TM-721A	MICROCOMPUTER LOCK-UP
ASB-0931	TM-721A	LOW/NO VHF TRANSMIT POWER
ASB-0932	TH-25/45	TSU-6 ERRATIC TONE ALERT FUNCTION
ASB-0933	TM-221A	NO TX IN HIGH POWER DUE TO VOLTAGE DROP
ASB-0934	TM-221A	FINAL MODULE/LOW POWER OUTPUT HINTS
ASB-0935	TM-321A	LOSS OF TX AUDIO WITH MC-48B
ASB-0936	TM-721A	S-METER DEFLECTION DUE TO PULSE NOISE
ASB-0937	TM-721A	AF PA WHITE NOISE WITH UNIT SQUELCHED
ASB-0938	PS-430	VOLTAGE INCREASE WITH TH-205/215
ASB-0939	TH-25/45	DISABLE AUTOMATIC POWER OFF FUNCTION
ASB-0940	INTERNAL	DELETED
ASB-0941	MANY	SERVICE MANUAL RX SECTION LEVEL DIAGRAMS
ASB-0942	MANY	SERVICE MANUAL TX SECTION LEVEL DIAGRAMS
ASB-0943	INTERNAL	DELETED

ASB-0944	TH-205/215/415	VOLUME/SQUELCH CONTROL IMPROVEMENTS/BRACKET
ASB-0945	TH-205	RCV SIGNAL TO NOISE RATIO IMPROVEMENTS
ASB-0946	TH-215/415	TX SIGNAL TO NOISE RATIO IMPROVEMENT
ASB-0947	TS-440S	OPERATION WITH THE MC-85
ASB-0948	TS-440S	NOTCH FILTER LOW FREQUENCY IMPROVEMENTS
ASB-0949	TS-440S	PROTECTING Q33 FROM SHORT ON REMOTE PLUG
ASB-0950	TS-440S	CASE SCREWS BINDING IN THE HEAT SINK
ASB-0951	TS-940S	ERRATIC DISPLAY (REMOVE THE ROM SOCKET)
ASB-0952	TS-440S	INTERMITTENT OPERATION/ROM SOCKET
ASB-0953	MC-55	CHANGE IN MIC ELEMENT (T91-0328-08)
ASB-0954	TS-820S	TA7201P SUBSTITUTION PARTS KIT
ASB-0955	INTERNAL	PARTS ORDER DESK FOR DEALERS
ASB-0956	TM-531A	20 MHZ OFFSET MODIFICATION
ASB-0957	TH-75A	NO TX ON VHF WHEN IN VEHICLE
ASB-0958	MC-44DM	INCREASE IN AUDIO LEVEL
ASB-0959	TS-950SD	SPEECH PROCESSOR NOISE
ASB-0960	TS-950SD	LOW VS-2 AUDIO
ASB-0961	TS-950SD	N.B.GATE SWITCHING NOISE
ASB-0962	TS-950SD	RX-TX SWITCHING TIME WITH AMP
ASB-0963	TS-950SD	RX DIGITAL NOISE ON 10 & 15 METERS
ASB-0964	TS-950SD	TWO SECOND TX DELAY WITH MONI SWITCH ON
ASB-0965	TM-731A	DELETED
ASB-0966	TM-231A	INTERMITTENT MEMORY LOSS
ASB-0967	TM-701A	INTERMITTENT MEMORY LOSS
ASB-0968	TH-25AT/TH-45AT	KEYPAD OVERLAY REPLACEMENT
ASB-0969	INTERNAL	DELETED
ASB-0970	SM-230	BANDSCOPE ATTENUATION MOD
ASB-0971	TS-950SD	RECEIVER NOISE WITH VOLUME AT MINIMUM
ASB-0972	TM-631/TM-731	MEMORY LOSS
ASB-0973	TS-440S	PLL UNLOCK IN VCO'S DUE TO GLUE
ASB-0974	TS-440	PLL UNLOCK / PLL #1
ASB-0975	SM-230	RTTY CROSS PATTERN MODIFICATION
ASB-0976	TH-26A	INTERNAL BIRDIES
ASB-0977	TM-731/TM-631	144MHZ FINAL BOARD CHANGE
ASB-0978	TH-75A	INTERMITTENT MEMORY LOSS
ASB-0979	INTERNAL	DELETED
ASB-0980	TM-941A	BPF ALIGNMENT TOOL
ASB-0981	TH-77A	MEMORY LOSS WITH LOW BATTERY VOLTAGE
ASB-0982	TS-950SD	TX IMAGE ON 18.115 MHZ CAUSING DISTORTION
ASB-0983	MC-48	MIC ELEMENT CHANGE /INSTALLATION
ASB-0984	TS-950SD	80 METER SPURIOUS EMISSION ON 80 METERS
ASB-0985	PB-2/PB-12	BATTERY CURRENT LIMITING RESISTOR FAILURE
ASB-0986	TS-440S	S/M ALIGNMENT PROCEDURE UPDATES
ASB-0987	TH-205/215/315/415	NEW PTT KNOB INSTALLATION
ASB-0988	TS-940	MRF-485 DRIVER TRANSISTOR CHANGES (BLUE DOT)
ASB-0989	DRU-2	ERRATIC PLAYBACK/MEMORY LOSS
ASB-0990	TS-950S	FINAL AMP.BIAS CIRCUIT CHANGE
ASB-0991	TS-950S	REAR COOLING FAN / POWER DOWN
ASB-0992	DSP-100	6 PIN CABLE CHANGE
ASB-0993	TH-27A	LOW TX POWER WITH TOSHIBA MODULES
ASB-0994	TS-450/TS-690	DISTORTED TX AUDIO WITH PACKET TERMINAL
ASB-0995	TS-450/TS-690	CALIBRATION CABLE CHANGE
ASB-0996	TM-732A	440 RECEIVE INTERFERENCE FROM 2 METER XMIT
ASB-0997	TH-78A	CLONE FAILURE W/ME-1
ASB-0998	TS-950SDX	RANDOM TRANSMIT WHEN MODE IS CHANGED
ASB-0999	TS-950SDX	NO BEEP IN HEADPHONE WHEN USING MONO PHONES
ASB-1000	TS-850S	DISTORTED TX WITH PACKET TERMINAL

ASB-1001	TS-950SDX	DISTORTED DRU-2 TRANSMIT AUDIO
ASB-1002	TS-450/TS-690	DISTORTED TX WITH PACKET TERMINAL
ASB-1003	TS-950SDX	K1EA VER.8 PROGRAM PROBLEMS - NEW EPROM
ASB-1004	TS-450S	POOR TRANSMIT AUDIO FREQUENCY RESPONSE
ASB-1005	TM-732A	CHANGE IN VALUE OF CHIP FUSE
ASB-1006	TS-850S	LOW OR NO RECEIVE SENSISTIVITY/NO AUDIO
ASB-1007	TS-950SDX	SPEECH PROCESSOR ADJ / EXCESSIVE NOISE
ASB-1008	TH-78A	CALL CH. TONE FREQ PROBLEM WITH TSU-7
ASB-1009	TS-950SDX	3RD ORDER IMD IMPROVMENTS
ASB-1010	AT-50	AT-50 BLOWS ACCESSORY FUSE IN TS-50
ASB-1011	TM-732A	LOW CROSS-BAND REPEAT AUDIO
ASB-1012	TS-950SDX	KEY CLICK WITH BUG TYPE KEY
ASB-1013	TH-78A	LEFT ENCODER INOPERATIVE
ASB-1014	TM-732A	NOISE AT SQULECH ON/OFF ON OTHER BAND
ASB-1015	TS-50S	LITHIUM BATT. REPLACEMENT CAUTION
ASB-1016	TS-950	HUM WITH MONITOR ON S/N < 1060XXX
ASB-1017	TS-950	NOISE WHEN NB1 ON FOR SUB RECEIVER
ASB-1018	TS-950	14.200 MHZ TRANSMIT SPUR S/N <1010XXX
ASB-1019	TS-950	LOW PWR.OUTPUT AFTER TEMPERATURE PROTECT
ASB-1020	TS-950	INFINITE SWR AT BEGINNING OF TRANSMISSION
ASB-1021	TS-950	SMOKE FROM ANTENNA TUNER
ASB-1022	MC-44DM	INTERMITTENT AUDIO
ASB-1023	TM-732A	S-METER SQUELCH SCAN IMPROVEMENT
ASB-1024	TS-950SD	TRANSMIT SPURS
ASB-1025	AT-50	BLOWS ACCY FUSE IN TS-50
ASB-1026	TS-950SDX	CLICK NOISE WHEN NOTCH IS ON
ASB-1027	TM-732A	PROT OF Q201 (FIRST RF AMP) 440 SIDE
ASB-1028	TH-78/28/48	DIFFICULT BATT. INSERTION
ASB-1029	TM-742/942	28MHZ/50MHZ R/C XMIT FAILURE
ASB-1030	TS-50	"HELLO" DISPLAYED DURING TRANSMIT
ASB-1031	SMC-34	DISTORTED/MUFFLED AUDIO
ASB-1032	TS-450/TS-690	LOW MIC GAIN W/DSP-100
ASB-1033	TM-742/942	MICRO LOCKUP WHEN IN REMOTE OPERATION
ASB-1034	TS-850/VS-2	NO AUDIO FROM VS-2
ASB-1035	TS-50	ANTENNA LEAD WIRE CONNECTION
ASB-1036	TS-450	PARTS CHANGES FOR DRIVER TRANSISTORS
ASB-1037	TH-28/TH-48	CTCSS TONE ERROR - 131.8,136.5,173.8 HZ
ASB-1038	TH-78	MICRO CHANGE - DISABLE 800 MHZ RECEIVE
ASB-1039	TH-48	MICRO CHANGE - DISABLE 800 MHZ RECEIVE
ASB-1040	TM-642/742/942	MICRO CHANGE - DISBALE 800 MHZ RECEIVE
ASB-1041	TM-411	MICRO CHANGE - DISABLE 800 MHZ RECEIVE
ASB-1042	TM-642/732/942	MICRO CHANGE - SUPERCEDES ASB-1033
ASB-1043	TS-950SDX	INSTALLATION OF YG-455S1
ASB-1044	TS-50	MECHANICAL NOISE FROM FINAL UNIT
ASB-1045	TS-950SDX	NO VFO B AFTER SPLIT OPERATION / MICRO CHANGE
ASB-1046	TS-850	S METER ADJUSTMENT
ASB-1047	TS-950SDX	CARRIER POINT ADJUSTMENT
ASB-1048	TH-78A	IMD IMPROVEMENT
ASB-1049	TS-850	CLICK NOISE WITH NOTCH ON
ASB-1050	TS-950SDX	SUB BAND RESIDUAL NOISE
ASB-1051	TM-732A	CONTROL PCB FOIL DAMAGE
ASB-1052	TS-950SD	SPUR ON 18.115
ASB-1053	TS-950SDX	CHANGE OF FINAL GATE RESISTOR TYPE
ASB-1054	AT-50	MECHANICAL STABILITY OF CASE
ASB-1055	MANY	USE OF HEATSINK COMPOUND
ASB-1056	TM-732	APC CIRCUIT MODIFICATION
ASB-1057	TH-22/42	MEMORY LOSS WHEN BATTERY RUNS DOWN

ASB-1058	TM-455A	CHANGE IN PIN DIODE
ASB-1059	TS-450S	CHANGE OF NOISY ENCODER
ASB-1060	TM-733A	PL TONE DISTORTION/AUDIBLE
ASB-1061	TM-733A	PL TONE BLEED THRU TO SPEAKER