

Kenwood service and technical support: Last Updated: 8/25/2017

K4EAA – Ken, FL, – EMAIL: ken@k4eaa.com , Web: www.k4eaa.com (Suspended Hybrid Repairs)

N9HE – Steve, AZ, Email: n9he@quarked.com

WB2KNR – Jim, NJ, Email: jimlamanteer@yahoo.com

AK4AA – David Lyndon, NC, Email: ak4aa36@gmail.com , Web: <http://oldhamdave.com/>

W0NTA – Dick, Greeley, CO, Phone: (970)381-6768 Email: dick@w0nta.com , Web: <http://www.w0nta.com>

K9TW – Terry, MI, Phone: (269)663-8943 Email: wagstw46@aol.com , Web: <http://www.k9tw.com>

WA8SAJ – Jeff, OH - Phone: (440)951-6406, EMAIL: wa8saj@ncweb.com , Web: <http://wb4hfn.com/Services/WA8SAJ/SAJ-Repair.htm>

HamRepair.com - Cal Fisher – TX, Phone: 214.476.5107, E-Mail: info@HamRepair.com , Web: <http://hamrepair.com/>

N0BXE, Affordable Radio Repair, Mike Alexander, Florence, CO. ,E-Mail: mike@affordableradiorepair.com Web:<http://www.affordableradiorepair.com/>

KA5IPF, Clif Holland, Avvid, Mabank, TX 75147 Phone: 214-850-0973 Email: clif@avvid.com Web: <http://www.avvid.com/> * (Also TS-940)

KE7OAY, Kenwood Restoration & Repair, Jim Showker, Eugene, Oregon, Email: jim@hybridrestore.com Web: <http://www.hybridrestore.com/>

K6ARU, Turner Radio, Lancaster, Calif., 616-945-9097 Email: k6aru@cwo.com

Midwest Technical Services, Watertown, Sdak, Phone: 605-882-1706, Email: tcmoes@yahoo.com ,Web Page: <http://www.midwest-technical.com/>

AK4AA, Dave Lyndon, Hot Springs, NC, Phone: 828-622-0115, email: ak4aa36@gmail.com Web: www.oldhamdave.com * (Also TS-940)

KC9INK, Walley, Indianapolis, IN, Does local repair work only, Phone 317 823 9380, E Mail wallydoc@yahoo.com ,*(Also TS-940)

K7ZS – Kevin Lahaie, Hillsboro, OR, Email: kevin@k7zs.com *(Also TS-940's)

Burghardt Radio Repair, Watertown, SD, Phone: (605) 886-7314, Email: service@burghardttradiorepair.com , Web: <http://www.burghardt-amateur.com/> *(Also TS-940's)

Avvid Electronics, 322VZ County Road 2714, Mabank, TX 75147, Phone: 214-850-0973, Email: clif@avvid.com , Web: www.avvid.com / (Only later radio's, no hybrids)

WB0CJB, Paul Kemp, Columbia, TN, Email: pckemp4@hotmail.com (Works on most Hybrid Kenwoods, Drakes, Kenwood, TS120, 130, 430 & 440 plus later models etc.)

KD7DNY – Walter Dilley, Email: walter.dilley@gmail.com Web: www.k7dny.com

Kenwood Parts:

K4EAA – KEN - EMAIL: ken@k4eaa.com , Web: www.k4eaa.com

Kenwood Hybrid Restoration & Repair, KE7OAY, Jim Showker, Oregon Email: jim@hybridrestore.com Web: <http://www.hybridrestore.com/>

KD7DNY – Walter Dilley, Email: walter.dilley@gmail.com Web: www.k7dny.com (Bought all of Bob Mansker, KE5TTF inventory) **(NEW WEB ADDRESS)**

Nationwide Radio & Eq. Sales LLC, Mark Olson, Suamico, Wi. 54173, Email: ke9pq@new.rr.com Phone: (920) 434-8097 **Web:**

<http://marketplaceadvisor.channeladvisor.com/StoreFrontProfiles/default.aspx?sfid=86409>

Ken's Electronics: 2825 Lake St., Kalamazoo, MI 49048, Phone: (269)345-4609, Web: www.kenselectronics.com/

East Coast – Phone: (800)632-3323, Web: <http://www.kenwoodparts.com/parts/index.php>

Radio Boatanchor Parts: TEL: 207-942-5745 xfrmrs@roadrunner.com Web: http://tubes_tubes_tubes.tripod.com/index.html

PacParts Inc., Phone: 800-421-5080, Web: <http://www.pacparts.com/>

Parts Description:

Band Switch Coupler:

1. K4EAA – KEN - EMAIL: ken@k4eaa.com , Web: www.k4eaa.com
2. Kenwood Hybrid Restoration & Repair, Email: jim@hybridrestore.com Web: <http://www.hybridrestore.com/>
3. East Coast P/N: D22-0409-05 - (L5) NYLON COUPLER R-5000 TS-830S TS-820S R-1000 www.eastcoasttransistor.com



TS-520, TS-820, TS-530, TS-830 Flat Pack RL1:

1. K4EAA – KEN - EMAIL: ken@k4eaa.com , Web: www.k4eaa.com
2. Kenwood Hybrid Restoration & Repair, Email: jim@hybridrestore.com Web: <http://www.hybridrestore.com/>
3. Online Components, Web: <http://www.onlinecomponents.com/keywordsearch.aspx?text=nf4eb-12v>



TS-520, TS-820 Antenna Relay:

1. Kens Electronics, Web: <http://www.kenselectronics.com/> P/N: 401013-S term 12VDC *replace MH4P-12VDC in T599D, TS520S, TS820*
2. Kenwood Hybrid Restoration & Repair, Email: jim@hybridrestore.com Web: <http://www.hybridrestore.com/>



Misc. Items:

TS-830 & TS-530 L41 Replacement - KD7DNY – Walter Dilley, Email: walter.dilley@gmail.com Web: www.k7dny.com **(NEW)**

TS-830 Rectifier board relay – Source unknown at this time...

TS-940 Relay Omron G6E134P-ST-US-DC12 , Digikey Panasonic part # 255-1473-ND

TS-520, 820, 530, 830 Drive Sprockets, email: NR6C@roadrunner.com , Web: <http://nr6c.com/sprocket.htm>

TS-520/820 Paddle Switch Handles, eBay user: [id_dude](https://www.ebay.com/username/id_dude), Search for "Kenwood Paddle Switch Handles" .

TL-922 upgrades, Kessler Engineering LLC, Ph: 937-458-3173, email: don@KesslerEngineeringLLC.com , Web: www.KesslerEngineeringLLC.com

Cabinet Paint - ACE Hardware, Rust Stop, Machine & Implement, Ford Gray Gloss, Item# 082901171393

